

Am Sophienhof 9 D-24941 Flensburg

Telephone: +49 461 940 2654 – 0 Fax: +49 461 940 2654 -8 E-Mail: info@johapack.de Flensburg, 09.03.2023

## **IMPORTANT CUSTOMERINFORMATION**

## Transport, storage and processing conditions

For the transport and storage of our packaging, we recommend temperatures between  $10 - 20^{\circ}$ C. Ideally, the temperature is between  $15 - 20^{\circ}$ C. Avoid high temperatures over  $40^{\circ}$ C as well as direct sunlight or direct proximity to heat sources – this can cause unwanted activation of the hotmelt.

The relative humidity should be at 50%. Too dry or too humid air leads to changes in the packaging material and makes it more difficult to process.

Avoid storage outdoors at all costs – even temporarily, e.g. during loading.

Generally, we recommend storing the unopened packaging material at least 24 hours prior the processing in the operating rooms to allow acclimatization.

Please fan out the bags so that they detach from each other before inserting them into the machine.

Make sure that opened goods are carefully packed again.

The storage period should not exceed 6 months.